

GOVERNMENT OF WEST BENGAL  
OFFICE OF THE EXECUTIVE ENGINEER  
SOUTH 24 PARGANAS DIVISION  
PUBLIC WORKS DIRECTORATE  
76, DR. DEODAR RAHAMAN ROAD  
(3<sup>RD</sup> FLOOR)  
KOLKATA – 700 033  
Phone (Office & FAX):-  
2422-0365 & 2422-0366



পশ্চিমবঙ্গ সরকার  
নির্বাহী বাস্তুরকার  
দক্ষিণ ২৪ পরগনা জুজি, পূর্ভ দপ্তর  
৭৬, ড: দেওদার রহমান রোড, চতুর্থ তল  
কোলকাতা - ৭০০ ০৩৩

দূরভাষ (কার্যালয় ও ফ্যাক্স)-  
(০৩৩) ২৪২২-০৩৬৫ এবং ২৪২২-০৩৬৬  
ই-মেল :- eessdivn1@gmail.com

E-mail:- eessdivn1@gmail.com

Memo No. - 2179


Date - 24.11.2022

## TO WHOM IT MAY CONCERN

Certified that the existing building BISHOP GEORGE MISSION SCHOOL at Ghatakpur, P.O. – B-Gobindopur, P.S. – Bhangore, District – South 24 Parganas, PIN- 743 502, West Bengal (J.L. NO. 100, R.S. Dag No. 2346, 2348, R.S. Khatian No. 678, ~~678~~ ~~678~~ under Prangang Gram Panchayet, Bhangore – I Panchayet Samity) comprised of Ground Floor & First Floor owned and occupied by BISHOP GEORGE MISSION SCHOOL have complied with the Building Safety Requirement in accordance with National Building Code Rules and verified by the officer concerned of P.W.D., Baruipur on 20-09-2022 in the presence of Assistant Engineer, Baruipur Sub Division, P.W.D. and that the building / premises is fit for the occupancy up to Class 1 to Class 10 with effect from 11-04-2021 for a period of 50 years in accordance with a rule and subject to compliance of specific condition as appended according the available record shown by the School Authority.

1. Every after three years inside and outside of School Building should be painted by the School Authority.
2. On regular basis the cracks on the wall and other parts to be mending properly and taken care by the School Authority.
3. Surrounding adjacent areas of the building to be filled in and proper care to be taken to remove all the gaps and holes by the School Authority.



  
24/11/2022  
EXECUTIVE ENGINEER, P.W.D.  
SOUTH 24 PARGANAS DIVISION  
